
396-02-7371

501-5000 Analog Height Sensor Splitter Harness

About

The Analog Height Sensor Splitter Harness (PN 201-7298Y1) allows multiple SurePoint systems to share a single height sensor input, typically a frame-mounted potentiometer for John Deere drawn planters.



Installation

To install:

1. Unplug the existing implement harness from the height sensor output.
2. Connect the single end of the Height Switch Splitter Harness into the height sensor output.
3. Connect the existing implement harness into the connector labeled **Planter Opt 1**.
4. If used, connect the height sensor input from MVX or John Deere rate control into the connector labeled **Planter Opt 2**.
5. If used, connect the height sensor input connectors from any additional system harnesses to the splitter connectors labeled **Height Sensor Out 1** or **Height Sensor Out 2**.

TIP
A 3-pin WP harness extension may be required (PN 206-03-10449)

NOTE
A 3-pin to 2-pin adapter is not needed when using the Analog Height Switch Splitter Harness.

SurePoint Ag Systems