

## **396-4969Y1** Flow Indicator Offset Bracket

## **Mounting Instructions**

Kit Number: 515-02-100800

**Kit Description:** Offset Mounting Bracket for Flow Indicators/Sentinel - for use on Stack Fold/Wing Fold (Add-U-bolt)

ITEM NO.	PART NUMBER	DESCRIPTION	QTY.
1	300-080100-5	1/2" x 1" Hex Head Bolt	2
2	323-08	1/2" Flange Nut	2
3	330-08	1/2" Flat Washer	2
4	400-3985Y1-BK	Flow Indicator Offset L Bracket	1


1/2" U-Bolt will be included after specifying size.




## Step by Step Instructions



- 1. Loosely mount 400-3985Y1 to toolbar using two (2) U-bolts, nuts, and washers.
- 2. Loosely mount desired Flow Indicator/Sentinel Mounting Bracket to 400-3985Y1 using the hardware provided in the kit.
- 3. Tighten everything down once brackets are in their desired location.





396-5579Y1 - Flow Indicator Offset **Bracket Mounting Instructions** 

Page 2 © 2022 SurePoint Ag Systems, Inc. Revised: 7/8/2022

Step 1