



396-4001Y1 Manual High Pressure SureBatch Parts List Manual



NOTE: Make Sure Pump is Primed Before Operation. DO NOT RUN PUMP DRY



Overall System Layout



15 Gallon Cone Bottom Tank
PN: 727-05-INFD15-19
Tank Stand
PN:727-29-INFD15ST

Manual High Pressure
SureBatch
(See page 3)



Inlet Plumbing Hose Kit
(See page 4)



Discharge Hose Kit
(See page 5)



Manual High Pressure SureBatch Parts List



3/4" Strainer Assembly
PN: 521-06-3704Y1

SS Braided Hose
PN: 283-01-038-06FPT

1/2" AG200 Hose—2 feet
PN: 280-050-AG200



400 PSI Pressure Gauge
PN: 137-LFG400-BM


Check Valve
PN: 136-01-C600SS

3/8" MPT x #6 JIC Swivel Fitting
PN: 161-09-6MP-6FJX

115VAC Motor
PN: 210-3413Y1

Procon Metal Clamp
PN: 352-01-1113

Procon Pump—1.16 GPM
PN: 290-12-103A070R3



110 Volt Power Chord

ON/OFF Switch



Inlet Plumbing Kit Parts List





Inlet Plumbing Kit Parts List

3/8" x 20' Hose (Male JIC)
PN: 283-038-06MJIC

Plumb to SureBatch Discharge



1-3/4" Acme Tank
Connection Kit
PN: 545-01-100100
OR
2-1/4" Acme Tank
Connection Kit
PN: 545-01-100150

Connects to NH3 Tank