396-7010Y1 Sentinel 1.6.0 & Newer Harness Notification


When installing this harness you must have Sentinel software version 1.6.0 or newer installed for it to work correctly. To check your software version



Press



This will take you to the screen that shows Sentinel ECU Version. Highlighted in below image in Red



Note: If you don't have Software version 1.6.0 or newer you must update your Sentinel ECU. Contact your local dealer for support.

SurePoint Ag Systems: 866-626-3670