

Marksman Software Release Notes

Version 2.0.5 – 7-8-2024

Issue:

IP address not available on screen. No check for SIM card presence. Incompatible with mainboard version A12.

Solution:

- Added IP address to screen.
- Added bigger chem cal number capability (R & D Request)
- Added SIM card check to disable modem and report SIM missing.
- Added code to allow operation on mainboard version A12.

Version 2.0.4 – 2-20-2023

Issue:

Modem did not provision correctly.

Solution:

Found that the screen command was not tied to any action in the program.

Telling the PROV: command to Go did not actually trigger the modem provision process. The missing program link has been added back in and this functionality has been corrected.

Version 2.0.3 – 12-14-2022

First production version. This should be functionally identical to version 1.4.7, but the screens have been redesigned – with regard to what is displayed – and the processor was changed.